


T-Angle linear actuator connectors

for linear actuators Ø30, Ø40, Ø50, Ø60











3 **Identification no.**

2 with 2 Stainless Steel-Clamping screws DIN 912





1		2							
d_1 Bore B **without** slide insert	Bore G **with** slide insert	**d_2** Clamping bore B	**d_3** Clamping thread	**d_4** Mounting screw on the follower	**k_1** Clamping length	**k_2** Clamping length	Length **l**	**m**	Clamping kit for d_3
B 30	G 30	B 30	M 8	M 4	40	42,5	92	60	GN 911-M 8-32
B 40	G 40	B 40	M 10	M 5	56	62	129	88	GN 911-M10-40
B 50	G 50	B 50	M 10	M 6	65	75	148	103	GN 911-M10-55
B 60	G 60	B 60	M 10	M 8	80	80	177	125	GN 911-M10-55

Specification

4

- Aluminum
  plastic coated
  black, RAL 9005, textured finish ● SW
- Guide bores / Clamping bores
  mechanically machined
- Slide insert
  Plastic (PA / PTFE)
- Socket cap screws DIN 912
  Stainless Steel AISI 304
- Hexagon nuts DIN 985
  Stainless Steel AISI 304
- *Stainless Steel characteristics → Page 1489*
- *Plastic characteristics → Page 1483*
- RoHS

Accessory

- Clamping kits GN 911 → *Page 1242*

Information

GN 192.1 T-angle linear actuator connectors are normally supplied **mounted** only in connection with a linear actuator and for function control.

By means of the clamping screw on the guide bore d_1 the movement can either be set or the linear actuator connector can be clamped (after setting of final adjustment).

The standard version of the clamping screws are socket cap screws with hexagonal socket DIN 912. They can be replaced by clamping kits GN 911 (article code see table of dimensions).

see also...

- *Construction tubes GN 990 → Page 1277*
- *Linear actuators GN 291 → Page 1326*
- *Linear actuators GN 292 → Page 1328*
- *Linear actuators GN 293 → Page 1329*

How to order

1 2 3 4

GN 192.1-G30-B30-2-SW

1	d_1
2	d_2
3	Identification no.
4	Finish